# NASA TECHNICAL MEMORANDUM

### NASA TM X-73322

(NASA-TH-X-73322) EXTERNAL TANK GASEOUS CYYGEN LINE SIMULATED LIGHTNING TESTS (NASA) 04 p HC \$4.00 CSCL 228 N76-28294

Unclas G3/18 47946

# EXTERNAL TANK GASEOUS OXYGEN LINE SIMULATED LIGHTNING TESTS

By Hubert E. Smith and R. M. Avery Materials and Processes Laboratory

July 1976

NASA

George C. Marshall Space Flight Center Marshall Space Flight Center, Alabama

MSFC - Form 3190 (Rev June 1971)

| Microsophia  |   |   |
|--|---|---|
|  | · ·   |   |
| 1 Report No.   | 2. Government Accession No.   | 3. Recipient's Catalog No.  |
| NASA TM X-73322  |   |   |
| 4. Title and Subtitle  |   | 5. Report Date  |
|  |   | July 1976   |
| External Tank Gaseous Oxygen Line Si   | mulated Lightning Tests   | 6. Performing Organization Code   |
| 7. Author(s)   |   | 8. Performing Organization Report No  |
| Hubert E. Smith and R. M. Avery  |   |   |
| <u> </u>   |   | 10. Work Unit No.   |
| 9. Performing Organization Name and Address  |   |   |
| George C. Marshall Space Flight Cent   | er  | 11. Contract or Grant No.   |
| Marshall Space Flight Center, Alabam   |   |   |
|  |   | 13 Type of Report and Period Covered  |
| 12. Sponsoring Agency Name and Address   |   | Technical Memorandum  |
| National Aeronautics and Space Admin   | istration   | 14. Sponsoring Agency Code  |
| Washington, D.C. 20546   |   |   |
| 15 Supplementary Notes   | · · · · · · · · · · · · · · · · · · ·   |   |
| Prepared by Materials and Processes  | Laboratory, Science and Engineering   |   |
| 16 Abstract  |   |   |
| oxygen pressurization line. This line, approximately $4.14\times10^6~\text{N/m}^2$ gage p ductor. Questions have been raised as tion as to the damage that might occur | valuate the effects of lightning strikes of designed to conduct gaseous oxygen at ressure (600 psig) and 302°C (575°F), as to the potential hazard of this line as a to the pressurization line, and the adjact investigation was from above the cone tude. | a pressure and temperature of may also act as a lightning con- a lightning conductor with specula- acent thermal protective surfaces, |
| Tests were performed on samp   | les of thin wall stainless steel tubing fi  | lled with gaseous oxygen under  |

Tests were performed on samples of thin wall stainless steel tubing filled with gaseous oxygen under simulated flight conditions. These tests were performed according to, and exceeding, the Shuttle Lightning Protection Specification JSC-07636, Revision A, for Component Testing. No specimen malfunctions occurred when the tests were conducted according to JSC specifications.

During the intermediate current tests, when the JSC specifications were deliberately exceeded to cause sample failures, there were no signs of flame, the holes remained small, and the flow of gaseous oxygen extinguished the arc. Some samples did burst along damaged areas during the 400 amp swept stroke tests of 0.79 m/s (2.6 ft/s), but were tested at a simulated velocity far below the test specification requirements of 19.5 m/s (64 ft/s).

Based on the JSC specifications and the results of these tests, it is concluded that a lightning strike will not cause a malfunction of the Shuttle External Tank gaseous oxygen line made of the representative material tested.

| 17 Key Words (Suggested by Author(s))  |                          | 18. Distribution Statement |                  |           |
|--|--------------------------|----------------------------|------------------|-----------|
|  |                          | Unclassified — Unli        | mited            |           |
| 19. Security Classif. (of this report) | 20. Security Classif. (d | of this page)              | 21. No. of Pages | 22. Price |
| Unclassified                           | Unclassified             |                            | 34               | NTIS      |

## **ACKNOWLEDGMENTS**

Mr. L. K. Swaim, Mr. John R. Rasquin, and Mr. W. J. Reed of the Materials and Processes Laboratory, Marshall Space Flight Center, are to be commended for their dedicated effort in helping to design the test facility, obtaining and making the required components, and supporting the preliminary tests.

# TABLE OF CONTENTS

|    |                        | P <b>a</b> ge |
|----|------------------------|---------------|
| I. | INTRODUCTION           | 1             |
| п. | DESCRIPTION OF TESTS   | 1             |
|    | A. High Current Tests  | 2<br>2        |
|    | C. High Altitude Tests | 4<br>4        |
| π. | CONCLUSIONS            | 6             |

# LIST OF ILLUSTRATIONS

| Figure | Title  | Page |
|--------|--|------|
| 1.     | Diagrammatic representation of lightning model   | 7    |
| 2.     | Test facility for high and intermediate current  | 8    |
| 3.     | High and intermediate current test facility  | 9    |
| 4.     | Sample after high current test of 140 000 amps   | 10   |
| 5.     | Typical high current waveform  | 11   |
| 6.     | Typical intermediate current waveform  | 11   |
| 7.     | Inside surfaces of 5 intermediate current tests  | 12   |
| 8.     | Sample after 3 strikes in same area (hole 0.190 cm diameter)                                 | 13   |
| 9.     | Intermediate current deliberate puncture test  | 14   |
| 10.    | Test facility for 400 amp continuous current   | 15   |
| 11.    | Test facility for the 400 amps continuous current tests                                      | 16   |
| 12.    | 400 amp continuous current facility and test sample after a test over a prior are path       | 17   |
| 13.    | 400 amp test facility and test sample after the test of 0.79 m/s (2.6 ft/s) are travel speed | 18   |

# LIST OF TABLES

| Table | Title                                | Page |
|-------|--------------------------------------|------|
| 1.    | High Current Tests                   | 19   |
| 2.    | Intermediate Current Tests           | 20   |
| 3.    | High Altitude Tests                  | 22   |
| 4.    | 400 Amp Stationary Test              | 23   |
| 5.    | 400 Amp Swept Stroke (Sample 1)      | 24   |
| 6.    | 400 Amp Swept Stroke (Sample 2)      | 25   |
| 7.    | 400 Amp Swept Stroke (Sample 3)      | 26   |
| 8.    | 400 Amp Swept Stroke Test (Sample 4) | 27   |

#### TECHNICAL MEMORANDUM X-73322

# EXTERNAL TANK GASEOUS OXYGEN LINE SIMULATED LIGHTNING TESTS

#### I. INTRODUCTION

Artificial lightning tests have been carried out on samples of stainless steel tubing filled with gaseous oxygen (GOX) at simulated flight conditions of  $4.14 \times 10^6~\rm N/m^2$  gage pressure (600 psig) and 302°C (575°F). The purpose of these tests was to evaluate possible lightning damage to the GOX line that extends along the outside of the Shuttle External Tank (ET). These tests were performed according to, and exceeding, the Shuttle Lightning Protection Specification JSC-07636, Revision A, for Component Testing. No malfunctions occurred when the tests were conducted according to JSC test specifications.

Some tests, which exceeded the JSC specification, were conducted to deliberately cause a test specimen puncture. These tests were to evaluate the possible damage that could result from the escaping hot GOX in the presence of hot metal or lightning hang-on. Based on a test specification minimum vehicle velocity of 19.5 m/s (64 ft/s) and from the results of these tests, it is concluded that there will be no malfunction of the noninsulated GOX line as a result of a lightning strike.

#### II. DESCRIPTION OF TESTS

A diagrammatic representation of a lightning model is shown in Figure 1. According to the Shuttle Lightning Protection Test Specification, JSC-07636, Revision A, Appendix  $\Lambda$ -1, Deviation, the GOX pressurization line will only be required to withstand the lightning model's second return stroke at a vehicle minimum velocity of 19.5 m/s (64 ft/s). This model can be represented for the purposes of testing by a high current, an intermediate current, and a 400 amp continuous current. The current waveforms required by the test specifications for testing the GOX line are as follows:

- a. High Current Test A 10 kHz damped sinusoidal waveform, 50 000 amp peak.
- b. Intermediate Current Test A waveform with 1 ms rise time and a 2 ms fall time to 50 percent amplitude and a peak current of 2500 amps.
- c. 400 Amp Continuing Current Test A 400 amp swept stroke current at a simulated vehicle velocity of 19.5 m/s (64 ft/s).

All of the GOX line samples used in these tests were either 304 or 321 stainless steel tubing, 5.08 cm (2 in.) in diameter with a wall thickness of 0.051 cm (0.020 in.). A stainless steel plate was welded to each end of the sample and fitted with a tubing connector. For the tests, the samples were heated to  $302^{\circ}$ C (575°F) and filled with GOX, from a continuous flow regulator, to a pressure of  $4.14 \text{ N/m}^2$  gage pressure (600 psig) to simulate flight conditions.

## A. High Current Tests

The test facility used for the high current test is shown in Figures 2 and 3. A photograph of a typical test current waveform is shown in Figure 5. Tests were conducted with a peak current ranging from 60 000 to 140 000 amps. The external damage to the GOX line sample, after the 140 000 amps simulated lightning strike, is shown in Figure 4.

There was very little damage to the GOX line samples from these high current, short duration tests (Table 1). The test specimens had extensive external metal movement and discoloration (Fig. 4) but very little wall thinning. The wall thinning was only 0.008 cm (0.003 in.) after the test of 140 000 amps.

### B. Intermediate Current Tests

The test facility shown in Figures 2 and 3 was used for the intermediate current tests. A photograph of a typical test current waveform is shown in Figure 6, and a photograph of the inside surfaces of five lightning strike tests is shown in Figure 7. Three of these samples are of single strike tests, where no punctures occurred. The other two samples are of multistrike tests in the same area on the specimen to purposely obtain a sample puncture. The external surface area and hole, after a multistrike test, is shown in the photograph of

Figure 8. It was necessary to have a puncture occur from a simulated lightning strike to assess the damage caused from the escaping hot oxygen in the presence of hot metal or a hot spark. Although the actual test current waveform did not meet the test specification curve width, the peak current amplitude was much higher, and the total energy discharged into the sample exceeded specifications.

It should be noted that no problems occurred when the artificial lightning tests were made within test specifications.

Results of single strike tests were as follows:

- 1. There was extensive external metal movement and discoloration.
- 2. There was discoloration of the internal wall (Fig. 7).
- 3. Wall thinned approximately 30 to 50 percent.
- 4. No puncture of the specimen occurred.

では、ここにというないないなどのではあるないのであるからないのでは、これのでは、ここにというないないないのでは、これのでは、これのでは、これのでは、これのでは、これのでは、これのでは、これのでは、これのでは、

Results of multistrike tests were as follows:

- 1. First sample punctured with a second strike in the same area causing a small hole, approximately 0.010 cm (0.004 in.) in diameter, Figure 7.
- 2. Second sample punctured with a third strike in the same area causing a larger hole than the first, approximately 0.190 cm (0.075 in.) in diameter (Figs. 7 and 8).
- 3. GOX flow through the holes extinguished the arc in both samples (Fig. 9).
  - 4. GOX pressure was maintained despite the hole.
- 5. Metal around the holes was pushed out and ragged due to the outward flow of GOX.
- 6. High speed (5000 f/s) movie film was made of these tests showing the arc being extinguished.

A summary of the tests, test conditions, and test results are shown in Table 2.

## C. High Altitude Tests

These tests were made to determine the comparative effects of a lightning strike at ground level and at a high altitude. A simulated altitude of 15.24 km (50 000 ft) was chosen. The intermediate current test facility (Fig. 2) and current waveform (Fig. 6) were used to perform these tests. The sample and high current electrode were placed inside a vacuum chamber, and two series of tests were made under the same conditions, except for the reduced sample external pressure of 1.17 N/m $^2$  absolute (1.7 psia) to simulate an altitude of 15.24 km (50 000 ft).

Results of tests at atmosphere pressure were as follows:

- 1. Five strikes in the same area were required to puncture the sample.
- 2. The hole was approximately  $0.076 \times 0.152$  cm ( $0.030 \times 0.060$  in.). Edges were pushed out and jagged.

Results of high altitude tests (15.24 km) were as follows:

- 1. Twelve strikes in the same area were required to puncture the sample.
- 2. The hole was so small that a microscope was required to locate the opening.

A summary of the tests, test conditions, and test results are shown in Table 3.

## D. 400 Amp Continuing Current Tests

To tes, and evaluate the 400 amp continuing current portion of the lightning model, five samples were tested: one sample was used for a stationary test (Table 4), and four samples were used for the swept stroke tests (Tables 5 through 8). The facility shown in Figure 10 was used to perform all of the 400 amp tests. A photograph of the test facility and the GOX line sample is shown in Figure 11.

1. 400 Amp Stationary Test. This test, though exceeding specifications was performed to assess the damage to the GOX line from a possible burning around the edges of the puncture (causing a large hole) due to the hot GOX and a conceivable lightning current attachment to the line at the point of the puncture. The test was made by initiating the 400 amp arc on the steel tab (Fig. 10), turning the inert gas off, and then moving the arc onto the sample. The arc was then stopped and held over the puncture.

Results of 400 amp stationary test were as follows:

- a. Punch through occurred immediately.
- b. There was no flame.
- c. The hole remained small, approximately 0.178 cm (0.070 in.) diameter.
  - d. The GOX extinguished the arc.
  - c. The flow of GOX caused fast erosion of the hot electrode.

A summary of the tests, test conditions, and test results are shown in Table 4.

2. 400 Amp Swept Stroke Tests. The 400 amp swept stroke tests were made by initiating the arc on the steel tab (Fig. 10), turning the inert gas off, and triggering the travel mechanism to sweep the arc along the length of the sample. Several different arc travel speeds were tested with each sample.

Results of 400 amp swept stroke tests were as follows:

- a. No puncture occurred with an arc travel speed in excess of 0.91 m/s (3 ft/s).
- b. A test was made over a prior are path (Table 6); the sample burst along the prior are path upon are contact with the damaged section (Fig. 12).
- c. At 0.79 m/s (2.6 ft/s), the 400 amp are traveled approximately 18 cm (7 in.) along the sample before a puncture occurred, Table 8. The sample then burst along the traversed path of the arc (Fig. 13).


A summary of the tests, test conditions, and test results are shown in Tables 5 through 8.

#### III. CONCLUSIONS

When the tests were made in accordance with test specification JSC-07636, Revision A, no failure occurred in any of the test samples. Although there was a definite wall thinning during the intermediate current tests, there were no indications of a probable punch-through; but if a punch-through did occur, it should cause no specific problems because the flow of GOX would tend to extinguish any flame. In the intermediate current tests, when the specifications were exceeded and the samples punctured, there were no signs of flame, the holes remained small, the GOX extinguished the arc, and there was no loss of GOX pressure.

If a severe lightning strike did damage a section of the GOX line and a puncture did result, the damaged section would probably rupture or burst. However, this problem only occurred at simulated velocities of less than 0.79 m/s (2.6 ft/s) which is far below the swept stroke test specification minimum velocity requirement of 19.5 m/s (64 ft/s).

Based on the lightning test specification requirements and the results of these tests, it is concluded that a lightning strike should not cause a malfunction in the GOX line made from the materials tested and if the line is noninsulated. If the GOX line is insulated or covered with a thermal protective material, these tests may not be valid because of the increased lightning hang—on time. Therefore, the addition of any type of insulation to the GOX line will require additional testing of the new line configuration.



サール というかいのあれ 一般などないないないかかく こ

Figure 1. Diagrammatic representation of Eghtning model (note that the diagram is not to scale).




Figure 2. Test facility for high and intermediate current.




Figure 3. High and intermediate current test facility.



Figure 4. Sample after high current test of 140 000 amps.




Figure 5. Typical high current waveform.




Figure 6. Typical intermediate current waveform.




Figure 7. Inside surfaces of 5 intermediate current tests.

Figure 8. Sample after 3 strikes in same area (hole 0.190 cm diameter).



Time  $T_0 = 0$ 



Time  $T_1 = T_0 + 0.6 \text{ ms}$ 



Time  $T_2 = T_0 + 1.2 \text{ ms}$ 



Time  $T_3 = T_0 + 1.8 \text{ ms}$ 

GOX flow through hole in sample extinguishes arc. Arc and hole were made by the third intermediate current strike in the same area. Hole was 0.190 cm (0.075 in.) diameter.

Figure 9. Intermediate current deliberate puncture test.




Figure 10. Test facility for 400 amp continuous current.




Figure 11. Test facility for the 400 amps continuous current tests.




Figure 12. 400 amp continuous current facility and test sample after a test over a prior arc path.



Figure 13. 400 amp test facility and test sample after the test of 0.79 m/s (2.6 ft/s) arc travel speed.

TABLE 1. HIGH CURRENT TESTS

|                    | Tes               | st Conditions   |
|--------------------|-------------------|---|
| GOX pressure       |                   | $4.14 \times 10^{8} \text{ N/m}^2 \text{ gage pressure}$ (600 psig)   |
| GOX tem            | per <b>at</b> ure | 302°C (575°F)   |
| Test cur           | rent waveform     | Figure 5  |
| Test faci          | lity              | Figure 2  |
| Capacito           | r bank            | 360 μf, 18 000 J  |
| Test faci          | lity R            | Distributed line resistance   |
| Test faci          | lity L            | Distributed line inductance   |
| Material           |                   | 304 stainless steel   |
| • • • • •          | hickness          | 0.051 cm (0.020 in.)  |
| Diameter<br>Length |                   | 5.08 cm (2 in.)<br>27.94 cm (11 in.)  |
| Test               | Peak              |   |
| Strike             | Current           |   |
| No.                | (kA)              | Results   |
| 1                  | 60                | Slight surface damage and dis-<br>coloration  |
| 2                  | 90                | Slight surface damage and dis-<br>coloration  |
| 3                  | 140               | Considerable surface metal movement and dark discoloration with a minor wall thinning of approximately 0.008 cm (0.003 in.) |

TABLE 2. INTERMEDIATE CURRENT TESTS

|                       |                           | Test :                  | Nacifions   |
|-----------------------|---------------------------|-------------------------|---|
| -                     |                           |                         | $4.14 \times 10^6$ N/m <sup>2</sup> gage pressure (600 psig)  |
| GOX te                | mperature                 |                         | 302°C (575°F)   |
| Test cu               | rrent wave                | form                    | Figure 6  |
| Test fac              | cility                    |                         | Figure 2  |
| Capacit               | or bank                   |                         | 720 µf, 36 000 J  |
| Test fa               | cility R                  |                         | 1.35 ohms   |
| Test fa               | cility L                  |                         | 400 μΙΙ   |
| Materia               | ıl                        |                         | 304 stainless steel   |
|                       | thickness<br>neter<br>;th |                         | 0.051 cm (0.020 in.)<br>5.08 cm (2 in.)<br>27.94 cm (11 in.)  |
| Test<br>Strike<br>No. | Sample<br>No.             | Peak<br>Current<br>(kA) | Results   |
|                       |                           |                         | Photographs of the results of these tests are shown in Figure 7.  |
| 1                     | 1-15-2                    | 5,5                     | Single strike — extensive external damage, internal wall discoloration, wall thinning to 0.028 cm (0.11 in.), no puncture.  |
| 2                     | 2-15-1                    | 5,0                     | Single strike — extensive external damage, internal wall discoloration, wall thinning to 0.036 cm (0.014 in.), no puncture. |

TABLE 2. (Concluded)

| Test<br>Strike<br>No. | Sample<br>No.  | Peak<br>Current<br>(kA) | Results  |
|-----------------------|----------------|-------------------------|--|
| 3                     | 1-2-<br>20-2   | 5.5                     | First strike — extensive external damage.  |
| 4                     | 1-2-<br>20-2   | 5,0                     | Second strike same area — puncture, small hole 0.010 cm (0.004 in.) diamete., edges are pushed out and very ragged, GOX flow through hole extinguished are (Fig. 9). GOX pressure was maintained.                              |
| 5                     | 1-21-3         | 5.0                     | Single strike - extensive externa damage, internal wall discoloration, no puncture   |
| 6                     | 2-3-4-<br>21-3 | 5                       | First strike - extensive externa damage  |
| 7                     | 2-3-4-<br>21-3 | 5                       | Second strike same area - more<br>damage   |
| 8                     | 2-3-4-<br>21-3 | 5                       | Third strike same area - puncture, 0, 190 cm (0, 075 in.) diameter hole, edges pushed out and ragged. See Figure 8. GOX pressure was maintained. Some very good high speed movie film (500 frames/second) was taken this test. |

#### TABLE 3. HIGH ALTITUDE TESTS

#### Test Conditions

The atmospheric pressure tests and the simulated high altitude tests were conducted under the same conditions, except for the reduced sample external pressure to simulate 15.24 km (50 000 ft) altitude. These tests were made together for the purpose of comparing results. The intermediate current waveform of 5 kA peak was used for the tests.

| GOX pr  | essure     | $4.14 	imes 10^6$ N/m $^2$ gage pressure           |
|---------|------------|--|
|         |            | (600 psig)   |
| GOX te  | mperature  | 302°C (575°F)                                      |
| Test cu | rrent wave | form Figure 6                                      |
| Test fa | cılity     | Figure 2   |
| Capacit | or bank    | 720 µf, 36 000 J                                   |
| Test fa | cility R   | 1.35 ohms  |
| Test fa | cility L   | 400 μΗ   |
| Materia | al         | 321 stainless steel                                |
| Wall    | thickness  | 0.051 cm (0.020 in.)                               |
| Dian    | neter      | 5.08 cm (2 in.)                                    |
| Leng    | gth        | 30.48 cm (12 in.)                                  |
|         |            |  |
| Test    | Peak       |  |
| Strike  | Current    |  |
| No.     | (kA)       | Results  |
|         |            | <del></del>  |
| 1-5     | 5          | At atmospheric pressure of $1.01 \times 10^5$      |
|         |            | $N/m^2$ (14.7 psia), five strikes in the           |
|         |            | same area were required to puncture                |
|         |            | sample. The hole was approximately                 |
|         |            | $0.076 \times 0.152$ cm $(0.030 \times 0.060$ in.) |
|         |            | pushed out and jagged.                             |
| 1 10    | _          | A4   |
| 1-12    | 5          | At a pressure of $1.17 \times 10^4 \text{ N/m}^2$  |
|         |            | absolute (1.7 psia) simulating an                  |
|         |            | altitude of 15.24 km (50 000 ft),                  |
|         |            | twelve strikes in the same area were               |
|         |            | required to puncture the sample. The               |
|         |            | hole was so small that a microscope                |

was required to find the opening.

TABLE 4. 400 AMP STATIONARY TEST

#### **Test Conditions**

GOX pressure  $4.14 \times 10^6 \text{ N/m}^2 \text{ gage pressure}$ 

(600 psig)

GOX temperature 302°C (575°F)

Test current 400 amps continuous

Test facility Figure 10

Material 321 stainless steel
Wall thickness 0.051 cm (0.020 in.)

Diameter 5.08 cm (2 in.)
Length 30.48 cm (12 in.)

#### Test Procedure

- 1. Initiate arc on steel tab (Fig. 10)
- 2. Turn off inert gas.
- 3. Move are onto sample.
- 4. Hold are and hot electrode above puncture.

#### Test Results

- 1. Hole occurred immediately.
- 2. No flame, the hole remained small approximately 0.178 cm (0.070 in.)
- 3. The GOX extinguished the arc.
- 4. The flow of GOX croded the hot electrode.

TABLE 5. 400 AMP SWEPT STROKE (SAMPLE 1)

|                       |                                      | Test Conditions  |
|-----------------------|--------------------------------------|--|
|                       | Test current                         | 400 amps continuous  |
|                       | Test facility                        | Figure 10  |
|                       | Material                             | 321 stainless steel  |
|                       | Wall thickness<br>Diameter<br>Length | 0.051 cm (0.020 in.) 5.08 cm (2 in.) 30.48 cm (12 in.)                     |
| Test<br>Strike<br>No. | Arc Travel, m/s (ft/s)               | Results  |
|                       |                                      | GOX pressure - atmospheric   |
|                       |                                      | GOX temperature — ambient  |
| 1                     | 0.46 (1.5)                           | Sample pressurized after test - no leak.                                   |
| 2                     | 0.31 (1.0)                           | Sample pressurized after test - no leak.                                   |
|                       |                                      | GOX pressure $-4.14 \times 10^6$ N/m <sup>2</sup> gage pressure (600 psig) |
|                       |                                      | GOX temperature — ambient  |
| 3                     | 0.46 (1.5)                           | Punctured upon are contact with sample.                                    |
|                       |                                      | GOX extinguished are.  |

TABLE 6. 400 AMP SWEPT STROKE (SAMPLE 2)

|                       | Te                           | st Conditions  |
|-----------------------|------------------------------|--|
| GOX pressure          |                              | $4.14 \times 10^6$ N/m <sup>2</sup> gage pressure (600 psig)   |
| GOX ten               | nperature                    | Ambient  |
| Current               |                              | 400 amps continuous  |
| Test fac              | ility                        | Figure 10  |
| Materia               | 1                            | 321 stainless steel  |
| Wall<br>Diam<br>Leng  |                              | 0.051 cm (0.020 in.)<br>5.08 cm (2 in.)<br>30.48 cm (12 in.)   |
| Test<br>Strike<br>No. | Arc<br>Travel,<br>m/s (ft/s) | Results  |
| 1                     | 2.89 (9.5)                   | No puncture  |
| 2                     | 2.71 (8.9)                   | No puncture  |
| 3                     | 2.44 (8.0)                   | No puncture  |
| 4                     | 2.26 (7.4)                   | No puncture  |
| 5                     | 1.80 (5.9)                   | No puncture  |
| 6                     | 1.49 (4.9)                   | No puncture  |
| 7                     | 0.79 (2.6)                   | Sample burst. This test was over the same arc path as test number 6. Sample burst along the prior path upon are contact (Fig. 12). |

TABLE 7. 400 AMP SWEPT STROKE (SAMPLE 3)

|                                      | Te                           | st Conditions  |
|--------------------------------------|------------------------------|--|
| GOX pressure                         |                              | $4.14 \times 10^6$ N/m <sup>2</sup> gage pressure (600 psig) |
| GOX temperature                      |                              | 302°C (575°F)  |
| Test cur                             | rent                         | 400 amps continuous  |
| Test fac                             | ility                        | Figure 10  |
| Materia                              | l                            | 321 stainless steel  |
| Wall thickness<br>Diameter<br>Length |                              | 0.051 cm (0.020 in.)<br>5.08 cm (2 in.)<br>30.48 cm (12 in.) |
| Test<br>Strike<br>No.                | Arc<br>Travel,<br>m/s (ft/s) | Results  |
| 1                                    | 1.80 (5.9)                   | No puncture  |
| 2                                    | 1.49 (4.9)                   | No puncture  |

TABLE 8. 400 AMP SWEPT STROKE TEST (SAMPLE 4)

| Test Conditions                      |                              |   |
|--------------------------------------|------------------------------|---|
| GOX pressure                         |                              | $4.14 \times 10^6$ N/m <sup>2</sup> gage pressure (600 psig)  |
| GOX temperature                      |                              | 302°C (575°F)   |
| Current                              |                              | 400 amps continuous   |
| Test facility                        |                              | Figure 10   |
| Material                             |                              | 321 stainless steel   |
| Wall thickness<br>Diameter<br>Length |                              | 0.051 cm (0.020 in.) 5.08 cm (2 in.) 30.48 cm (12 in.)  |
| Test<br>Strike<br>No.                | Arc<br>Travel,<br>m/s (ft/s) | Results   |
| 1                                    | 1,58 (5,2)                   | No puncture   |
| 2                                    | 1.13 (3.7)                   | No puncture   |
| 3                                    | 0.91 (3.0)                   | No puncture   |
| 4                                    | 0.79 (2.6)                   | Sample burst. At 6.79 m/s (2.6 ft/s), the 400 amp are traveled 18 cm (7 in.) along the sample before a puncture occurred. The sample then burst along the traversed are path (Fig. 13). |

### **APPROVAL**

# EXTERNAL TANK GASEOUS OXYGEN LINE SIMULATED LIGHTNING TESTS

By Hubert E. Smith and R. M. Avery

The information in this report has been reviewed for security classification. Review of any information concerning Department of Defense or Atomic Energy Commission programs has been made by the MSFC Security Classification Officer. This report, in its entirety, has been determined to be unclassified.

This document has also been reviewed and approved for technical accuracy.

R. L. GAUSE

Chief, Engineering Physics Division

R. J. SCHWINGHAMER

Director, Materials and Processes Laboratory